

# Errata for FM3135

## **RAMTRON**

1850 Ramtron Drive  
Colorado Springs, CO 80921  
719-481-7000 FAX: 719-488-9095  
www.ramtron.com

<b>Errata Number</b>	001 (all date codes)
<b>Date</b>	Sept. 1, 2009
<b>Product</b>	FM3135 Integrated RTC/Alarm/FRAM & Embedded Crystal
<b>Product Marking</b>	FM3135-G

Ramtron has discovered a problem with the FM3135 device. The use of surface mount reflow solder process for device assembly may cause the actual RTC oscillator frequency to be shifted outside of the calibration range (as high as 1%). Ramtron recommends the user hand-solder the device to the printed circuit board. A solution to the problem is being investigated.

---