

# Errata for FM25L256

## RAMTRON

1850 Ramtron Drive  
Colorado Springs, CO 80921  
719-481-7000 FAX: 719-488-9095

**Errata Number**            001 (rev. AF, Date Code 0431)

**Date**                         August 24, 2004

**Product Marking**        FM25L256 (all package types)

Initial testing has identified a problem with FM25L256 Rev AF samples.

- 1) The device has functional problems under some conditions. For 25MHz operation,  $V_{DD}$  must be  $\geq 3.13V$  and  $T_A \leq 55^\circ C$ . For operation up to  $70^\circ C$ , SCK frequency must be  $\leq 23MHz$  and  $V_{DD}$  must be  $\geq 3.0V$ .

---

NOTE: The above issue will be resolved on the next die revision. Samples will be available in 4Q04.